

FIG. 1




FIG. 2




FIG. 3




FIG. 4





FIG. 5






FIG. 7




FIG. 8






FIG. 9





FIG. 10



# FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18

EXTENSION NUMBER	COMMUNICATION TERMINAL ADDRESS
1234	133. 144. 6. 10
3446	133. 144. 6. 9
5678	133. 144. 5. 1
⋮	⋮
8769	133. 144. 5. 6



FIG. 19






FIG. 20



# FIG. 21



# FIG. 22

337 NAME	311 EXTENSION NUMBER	312 COMMUNICATION TERMINAL ADDRESS
TANAKA	1234	133. 144. 6. 10
SUZUKI	3446	133. 144. 6. 9
SATOH	5678	133. 144. 5. 1
AZUMA	8769	133. 144. 5. 6

FIG. 23

